## Learning Objectives

- To learn the relief procedure in case of emergency situations to the living beings.
- To learn the road safety rules.
- To learn the handling of tools and equipments in the workshop.

## 1.0 INTRODUCTION

Safety rules are necessary to ensure owners and employees not to injure themselves or customers during operation in machines. Perfection is required before doing the job, during the job and after doing the job. For perfection in work, an operator should know the handling of machine and equipment in a safe manner. For example, a welder can use goggles to protect the eyes from the heat and ultraviolet radiation produced by the welding. Other safety devices can be used depending upon the job. Such procedures to use proper safety in devices and operation is called as safety rules. The following are the classification of safety rules depends on the place of work.

1. Safety in Shop floor
2. Self-Safety
3. Safety in Machines
4. Safety in Tools
5. Road safety rules
6. Vehicle safety rules

## 1.1 WORKSHOP SAFETY RULES

The following rules have been followed in the workshop to ensure the safety of all employees while operating machines. The majour safety equipments are shown in Fig 1.1.

1. Always wear helmet and shoe in the workshop.
2. Always walk on the designated path.
3. Don't talk or distract the other employees during work.
4. Without prior notice, do not disconnect or connect an electrical connection.
5. Operate the machine after proper training and permission from authorities.
6. Keep the tools in their designated places only.
7. Keep the board "Under Fault" in the faulty machines.
8. Keep the first aid box at appropriate places
9. Use appropriate dress code inside the work premises.
10. When working with machine tools or other equipment with rotating spindles, watches, rings, jewellery, loose clothing etc., are prohibited and long hair must be completely covered.
11. Use proper material handling equipments to transfer raw material.
12. Maintain clean and hygiene canteen, water and restrooms.
13. An operator should not operate the machine continuously for more than 8 hours. Provide break at the specified intervals.



AM_Unit_01.indd 2 12/20/2019 4:19:06 PM