

INSIDE THE TANK**▲ STARTER CRANK**

The water-cooled engine was started by four members of the crew turning a large crank handle.

► DRIVER'S SEAT

The driver sat to the commander's right. He had to bring the tank to a halt to turn it, which made it an easy target.

**▼ INTERIOR CONDITIONS**

The crew – commander, driver, and six gunners – worked in hot, cramped, noisy, fume-filled conditions. Bullets hitting the exterior sent steel splinters flying inside the tank, so the men wore protective clothing.

**▲ UNCOVERED ENGINE**

The engine was exposed so that it could be kept lubricated while running.

**▲ SHELLS**

A Mark V carried 207 high-explosive and case-shot rounds, stored on shelves beside the sponsons.

**◀ HATCH LEVER**

There were access hatches for the crew on the roof, on the sponsons, and also at the rear of the tank.