UNIT
1

METALLURGY



Harold Johann Thomas Ellingham (1897–1975)

Ellingham was a British physical chemist, best known for his Ellingham diagrams. Ellingham diagram summarizes a large amount of information about extractive metallurgy, and are useful in predicting the favourable thermodynamic conditions under which an ore will be reduced to its metal. Ellingham was able to compare the temperature stability of many different oxides. The phenomenon of reduction of metal oxides into free metal by carbon or carbon monoxide was known before Ellingham's time, but Ellingham demonstrated it in a scientific manner.

3HYHK4

Learning Objectives

After studying this unit, students will be able to

- describe various methods of concentrating ores
- explain various methods of extraction of crude metals
- apply thermodynamic principles to metallurgical processes
- predict the favourable conditions for the reduction process using Ellingham diagram
- describe the electrochemical principles of metallurgy
- apply the electrochemical principles in the extraction of metals
- explain the electrode reactions in electrolytic refining.
- list the uses of Al, Zn, Fe, Cu and Au

XII U1 Metallurgy - Jerald.indd 1 04-01-2021 12:41:31