
Types of winding in armatures



9.5.1 Progressive winding

In progressive winding, finishing end of a coil is connected to the starting end of a coil which is placed in the right side of the starting point as shown in the figure 9.3.




Fig. 9.3 **Progressive lap winding**

9.5.2 Retrogressive winding

In Retrogressive winding, finishing end of a coil is connected to the starting end of a coil which is placed in the left side of the starting point as shown in the figure 9.4.




Fig. 9.4 **Retrogressive winding**

9.5.3 Lap winding

As shown in the figure 9.5, winding in which successive coils arranged in the manner that they overlap each other is called Lap winding.




Fig. 9.5 **Lap winding**

9.5.4 Wave winding

As shown in the figure 9.6, winding in which successive coils arranged in the manner that it does not overlap each other and it forms like a wave form and hence it is called wave winding.

BEE_ENG_Chapter_09.indd 137 12/27/2019 10:35:54 AM