Evaluation

TA2I4B

PART-A

Choose the correct answer **(1 Marks)**

1. Heart of a motor is
   a) Stator
   b) Rotor
   c) Winding
   d) Bearings

2. The basic property needed for a good conductor is
   a) Low resistance
   b) High mechanical strength
   c) Best soldering property
   d) High dielectric strength

3. The diameter of the wire guage plate is generally
   a) 3 ¼ inches
   b) 3 ½ inches
   c) 3 ¾ inches
   d) 4 ¾ inches

4. The instrument used to measure the diameter of a conductor is
   a) Wire guage plate
   b) Feeler guage
   c) Dial guage
   d) Screw guage

5. Example for the liquid insulating material is
   a) Asbestos
   b) Varnish
   c) Glass
   d) Mercury

6. The winding placed in the rotating part of DC machine is
   a) Main field winding
   b) Armature winding
   c) Inter pole winding
   d) Compensating winding

7. The closed type of slots are used in
   a) Stators of small size motors
   b) Stators of medium size motors
   c) Stators of squirrel cage induction motors
   d) Rotors of squirrel cage induction motors

8. The value of back pitch will be
   a) Odd number
   b) Even number
   c) Fraction
   d) Decimal

9. The value of 'm' in simplex winding is
   a) 1
   b) 2
   c) 3
   d) 4

BEE_ENG_Chapter_09.indd 149 12/27/2019 10:36:02 AM