10. If a DC machine works as a motor, the law used to find the direction of flow of current in armature winding is
    a) Fleming's right hand rule
    b) End rule
    c) Fleming's left hand rule
    d) Ohm's law

11. The number of parallel paths of a DC lap winding is
    a) P/2
    b) 2P
    c) 2P
    d) 2

12. The number of parallel paths of a DC wave winding is
    a) P
    b) 2P
    c) P/2
    d) 2

13. The number of brushes in DC machines are
    a) Equal to the number of parallel paths.
    b) Equal to the number of slots.
    c) Equal to the half of the number of slots.
    d) Equal to the half of the number of poles.

14. The distance between two active sides of a coil in DC winding is
    a) Front pitch
    b) Coil pitch
    c) Back pitch
    d) Fractional pitch

15. The distance between the starting ends of two adjacent coil is
    a) Front pitch
    b) Back pitch
    c) Coil pitch
    d) Pole pitch

16. The type of winding used in DC armature is
    a) Main field winding
    b) Inter pole winding
    c) Open type winding
    d) Closed type winding

17. Pole pitch is referred to as
    a) The number of slots per pole
    b) The number of slots per phase
    c) The number of slots per pole per phase
    d) Half of the number of slots

18. In full pitched winding, the electrical degree between two coil sides of a coil is
    a) 60°
    b) 120°
    c) 180°
    d) 360°

19. The number of coils in single layer winding is
    a) Equal to the half of the number of slots
    b) Equal to the number of slots
    c) Equal to the half of the number of poles
    d) Equal to the number of poles

BEE_ENG_Chapter_09.indd 150 12/27/2019 10:36:02 AM