20. If the number of coils are equal to the number of slots, then the type of winding is
    a) Single slot winding
    b) Double slots winding
    c) Single layer winding
    d) Double layer winding

21. If the coil groups of a phase winding having unequal number of coils, then the winding is called as
    a) Half coil winding
    b) Whole coil winding
    c) Unbalanced winding
    d) Balanced winding

22. The number of coil groups in a phase of a full pitched winding is
    a) Equal to the number of poles
    b) Equal to the half of the number of poles
    c) Equal to the number of slots
    d) Equal to the half of the number of slots

PART-B

Answer the questions in brief (3 Marks)

1. What is the necessity of winding in motors?
2. What is conductor?
3. Mention the types to notify the size of the conductors and the instruments used to measure it.
4. With a neat diagram, explain the parts of a single turn coil.
5. What is lap winding?
6. What are the three types of windings used in AC machines?
7. What is concentric winding?
8. What is pole pitch?
9. Define pitch factor.
10. What is whole coil winding?

PART-C

Answer the questions in one page (5 Marks)

1. Draw the diagram of a gauge plate and explain the method of finding the guage number by it.
2. Explain the different type of pitches used in DC armature windings.
3. Explain the method of calculation for finding the number of coils and coil groups in AC winding.

BEE_ENG_Chapter_09.indd 151 12/27/2019 10:36:02 AM