iv Capital repairs or corrective maintenance

After many years of working, the machine operation should be stopped and dismantling the machines for doing this maintenance for replaced the damaged parts. It should be done in number of days with more cost.

10.2.5 Planned maintenance Project

If the electric machine is working continuously, properly and efficiently, then the following planned maintenance be carried.

i. The new motor should be placed in proper and give proper connection to it.

ii. The hand tools, instruments and part of the motor should be readily kept for immediate maintenance.

iii. If the efficiency of the machine is reduced, then dismantle and overhaul it properly.

iv. Do the emergency repairs immediately.

v. Replaced the old machines with a new one.

vi. The maintenance consists of the layout, connection and construction of the machines, lubrication materials, planned maintenance list, previous maintenance list etc.

vii. Proper training should be given to the workers about new machineries.

viii. The cost for one year maintenance should be planned and submitted.

10.2.6 Importance of maintenance

Proper maintenance, acquires the following advantages.

i. The problems caused in machines are prevented.

ii. Sudden breakdown in the machines are prevented.

iii. Major complaints and expenses are reduced.

iv. Electrical machines with rated efficiency can be achieved.

v. Achieve the target of proper production with materials without any interruption.

10.2.7 General maintenance works made in electrical machines

i. Open the terminal box once in six months and test the terminals whether they are tight.

ii. Remove the grease completely for once in a year and apply the new grease. The process of removing the grease is called as “Degreasing”. After cleaning the bearings, apply new grease on it. This process is called “Greasing”.

iii. If the electrical equipment does not use for six months, then the old grease should be removed and apply new grease before to start it.

iv. Over hauling should be done on electrical machines for a period of once in three years.At that time, dismantle the all parts of the machines and clean the stator, rotor, bearings, grease cups, front and back end covers and assemble it.

BEE_ENG_Chapter_10.indd 155 12/27/2019 10:39:26 AM