3. If the milli voltmeter reads high voltage, the coil connected to the segment is open.
4. If the milli voltmeter deflects in the reverse directions as shown in the figure, the coil connected with the segment is reversed.

Generally armatures are tested for insulation resistance and for shorted coils. Only when a fault in the armature winding is suspected, drop test is conducted. But the results from the drop test are more reliable.

Activities

1. Dismantle and assemble the electric machines.
2. Alignment test for Direct coupled machines.

Glossary

Motor	-	மின்னோடி
Stator	-	நிலையி
Rotor	-	சுழலி
Bearings	-	தாங்கிகள்
Pulley	-	சக்தி மாற்றுச் சக்கரம்
Balancing	-	சமநிலைப் படுத்துதல் அல்லது சம எடைப் பகிர்வு
Alignment	-	ஒத்தமைவு
Commutator	-	திசைமாற்றி
Brush	-	தொடுவி
End play	-	முனை இடிப்பு
End trust	-	முனை அசைவு
Growler	-	உருள் அடை உருமி

BEE_ENG_Chapter_10.indd 165 12/27/2019 10:39:27 AM