Evaluation

L3GXVM

Part–A

Choose the correct answer **(1 Marks)**

1. In motor electrical energy is converted in to _____ energy
   a. Electrical
   b. Mechanical
   c. Heat
   d. Magnetic

2. In electrical motor stator is made up of _____ material
   a. Silicon steel
   b. Cast-iron
   c. Mild steel
   d. Stainless steel

3. Bush bearings are lubricated with _____ material
   a. Lubrication oil
   b. Grease
   c. Vegetable oil
   d. Transformer oil

4. Core is made up of _____ material
   a. Silicon steel
   b. Cast-iron
   c. Mild steel
   d. Stainless steel

5. _____ bearings are used at load side
   a. Ball
   b. Roller
   c. Sleeve
   d. Ball & Sleeve

6. _____is the instruments used to remove the bearing
   a. Bearing puller
   b. feeler gauge
   c. Plum bob
   d. Tri square

7. Major repair is called_____
   a. Minor repair
   b. Preventive maintenance
   c. Routine maintenance
   d. Overhauling

8. To avoid direct and indirect loss which maintenance should be followed?
   a. Routine maintenance
   b. Preventive maintenance
   c. Major repair
   d. Breakdown maintenance

9. Alignment is called_____
   a. Gap between stator and rotor
   b. Motor shaft and load shaft should be in one line
   c. Motor shaft and load shaft should not be in one line
   d. Motor shaft and load shaft should be in opposite direction

BEE_ENG_Chapter_10.indd 166 12/27/2019 10:39:27 AM