5. The operator should not touch the rotating work or the grinding wheel.
6. The operator should not wear loose shirts and neck tie.
7. The work rest of a bench grinder should be placed close to the grinding wheel.
8. The speed of the vitrified grinding wheels should not exceed 2000 meters per minute.
9. When new wheels are used, the wheels should be kept minimum.

ACTIVITY

1. Arrange the students to visit nearby industry, to demonstrate about the different types of grinding machines and its operation.

10. If the job is in a magnetic chuck, extra grips should be placed around the work pieces.

Questions

Part I.

Choose the correct option **1 Mark**

1. The accuracy obtained by precision grinding is
   a. 0.000025 mm
   b. 0.0025 mm
   c. 0.00125 mm
   d. 0.00625 mm

XK3PMH

2. The cutting tool with several thousands of cutting edges is
   a. Lathe cutting tool
   b. Drill
   c. Grinding wheel
   d. Milling cutter
3. The heat generated during dry grinding will be
   a. 2000^0C
   b. 20^0C
   c. 1000^0C
   d. 1200^0C
4. Bond used for making elastic grinding wheel is
   a. Vitrified
   b. Silicate
   c. Shellac
   d. Resinoid
5. The grip with which the bond holds the abrasives is known as
   a. Grain size
   b. Grade of the grinding wheel
   c. Structure of the grinding wheel
   d. Type of abrasive

Part II.

Answer the following questions in one or two sentences **3 Marks**

6. What is meant by grinding?
7. Name any four types of grinding machines.
8. What is meant by centreless grinding?

XII BME_English version CHAPTER 04.indd 97 1/8/2020 1:43:09 PM