
End milling

End milling is a process of the machining by milling cutters which have cutting edges both on the end face and on the periphery.


5.8 Work holding devices

For effective machining operations, the workpieces need to be properly and securely held on the machine table. The following are the usual methods of holding work on the table. Large and irregular shaped workpieces are held on the milling machine table by 'T' –bolts and clamps. 'V' – blocks are used for holding cylindrical workpieces on the machine table in which key ways, slots and flats are to be machined. Angle plates are used to support the work when surfaces are to be milled at right angles to another machined surfaces.




Plain Vise

Vises are commonly used for holding work on the table due to its quick loading and unloading arrangement. There are mainly three types of vises namely plain vise, swivel vise and universal vise.



Swivel Vise



Universal Vise

Milling fixtures are useful when large numbers of identical workpieces are to be machined workpieces are held easily, quickly and accurately by milling fixtures.

XII BME_English version CHAPTER 05.indd 105 1/8/2020 1:42:10 PM