
Screwed arbor



The small cutters having threaded holes at the center are held by screwed arbors. It has a threaded nose at one end and adapters shank at the other end the shank of the arbor is mounted on the spindle.

5.10 Milling machine attachments

Milling machine attachments are intended for purpose of developing the range of operations, versatility, production capacity and accuracy of machining process. The different milling machine attachments are

1. Vertical milling attachments
2. Universal milling attachments
3. High speed milling attachments
4. Slotting attachments
5. Rotary table attachments
6. Indexing head attachments



Vertical Milling Attachment

Vertical milling attachments

A horizontal milling machine is converted into a vertical milling machine by the vertical milling attachment. Vertical milling attachment is mounted on the face of the column of the horizontal milling machine. The attachment along with the spindle can be swiveled to any angle for machining angular surfaces.

Universal milling attachments

By having the universal milling attachments the spindle of the machine can be swiveled about two perpendicular axes. This arrangement permits two spindle axis to be swiveled at practically any angle to machine any angular surface of the work.



Universal Milling Attachment

High speed milling attachment

This attachment is used to increase the regular spindle speeds by four to six times milling cutters of smaller diameters are operated efficiently at higher cutting speeds. This attachment is bolted to the face of the column and enables the cutter to be operated at speeds beyond the scope of the machine.

XII BME_English version CHAPTER 05.indd 107 1/8/2020 1:42:11 PM