
available. The work is done very slowly because of a single cutting edge. A flying cutter is shown in Figure.



Flying cutter

Form cutter

Form cutters have irregular profiles on their cutting edges to produce required outlines on the work. Concave and convex milling cutters are used to produce convex and concave surfaces respectively using gear milling cutters. Gears are machined corner round milling cutters are used for cutting a radius on the edges of the work with the help of thread milling cutter threads are milled on a specific form and size. Tap and reamer cutter are used for producing grooves or flutes in tap and reamers.

5.13 Elements of a plain milling


Cutter

The main parts and angles of a plain milling cutter as shown in Figure.

FZH4MZ

Body of cutter

It is the part of the cutter left after exclusion of the teeth.



Elements of a plain milling cutter

XII BME_English version CHAPTER 05.indd 111 1/8/2020 1:42:13 PM