
Face milling

The face milling is the operation performed by the face milling cutter rotated about an axis at right angles to the work surface. End mills and side & face milling cutters are also used at times to perform this operation. The depth of cut is provided to the table.




Face milling operation

Side milling

Side milling is the operation of machining a vertical surface on the side of a work piece by using a side milling cutter.

Straddle milling


It is the operation of production of two vertical surfaces on both sides of the work by two side milling cutters mounted on the same arbor. By using suitable spacing collars, the distance between the two cutters are adjusted correctly. The straddle milling is commonly used to produce square or hexagonal surface.



Straddle milling operation

Angular milling


Production of an angular surface on a workpiece other than at right angles to the axis of the milling machine spindle is known as angular milling. Example of angular milling is the production of the 'V' blocks.



Angular milling operation

Gang milling

It is the operation of machining several surfaces of work simultaneously by feeding the table against a number of cutters (either of same type or of different type) mounted on the arbor of the machine. This method saves much of machining time and mostly used in production work.



Gang milling operation

XII BME_English version CHAPTER 05.indd 113 1/8/2020 1:42:13 PM