Regulators

Separate regulators are fitted on both the cylinders. A regulator is used to control the working pressure of the gases. The working pressures of oxygen is 1Kg/cm^2 and acetylene is 0.15Kg/cm^2. Working pressure of these gases are altered according to the thickness of the metal parts of the joint.



Regulators

Two pressure gauges are fitted each on the oxygen cylinder and on the acetylene cylinder. One of the pressure gauges indicates the pressure of the cylinder and the other gauge indicates the working pressure of the specific gas.

Hoses


Separate hoses are used to connect the two cylinders with the welding torch through regulators. The colour of the hose from the oxygen cylinder is black and the one from the acetylene cylinder is red. These hoses carry the gases to the welding torch.



oxygen hose

acetylene hose

Welding torch



Welding Torch

Oxygen and acetylene reach the welding torch through the passages of hoses from the respective cylinders. These gases

XII BME_English version CHAPTER 07.indd 133 1/8/2020 1:40:25 PM