3. The pressure of acetylene in the cylinder of gas welding equipments is
   a) 16kg/cm^2
   b) 125kg/cm^2
   c) 100kg/cm^2
   d) 14 kg/cm^2
4. The pressure of oxygen in the cylinder of gas welding equipment is
   a) 16kg/cm^2
   b) 125kg/cm^2
   c) 100kg/cm^2
   d) 14 kg/cm^2

PWXR6W

5. Plastic welding is
   a) Pressure welding
   b) Resistance welding
   c) Fusion welding
   d) Arc welding
6. Fusion welding is
   a) Pressure welding
   b) Non-pressure welding
   c) Resistance welding
   d) Thermit welding

Part II.

Answer the following questions in one or two sentences — 3 Marks

7. Mention any three types of arc-welding.
8. State any three types of gas welding.
9. State any three types of welding related process.
10. How is the welding electrodes specified?
11. What are the types of electrodes?
12. Name the three types of flames generated in gas welding.
13. What are the types of welded joints?

Part III.

Answer the following questions in about a page — 5 Marks

14. Explain any two types of equipments used in gas welding.
15. Explain any one type flame obtained in gas welding with a diagram.
16. What are the advantages of gas welding?
17. Explain the oxy-acetylene cutting with diagram.
18. Explain Hard-facing with diagram.
19. Explain Soldering with diagram.

Part IV.

Answer the following Questions in detail. — 10 Marks

20. Explain arc welding with a diagram.
21. List out the arc welding equipments with a diagram.
22. What are differences between AC arc welding transformer and DC arc welding generator?
23. Explain carbon arc welding with a diagram.
24. Explain gas welding with a neat sketch.
25. List out the differences between arc and gas welding.
26. Sketch and explain resistance welding.
27. What are the safety precautions during the process of gas and arc welding?

XII BME_English version CHAPTER 07.indd 140 1/8/2020 1:40:27 PM