DO YOU KNOW?

The inventor of Lathe is Henry Maudslay, in the year 1797. He is also called as father of Machine Tools.




1.1 Introduction

Lathe is considered as one of the oldest machine tools and is widely used in industries. It is called as mother of machine tools. The first screw cutting lathe was developed by an Englishman named "Henry Maudlay" in the year 1797. Modern high speed, heavy duty lathes are developed based on this machine.

1.2 Turning

The primary task of a lathe is to generate cylindrical workpieces. The process of machining a workpiece to the required shape and size by moving the cutting tool either parallel or perpendicular to the axis of rotation of the workpiece is known as turning.

In this process, excess unwanted metal is removed. The machine tool useful in performing plain turning, taper turning, thread cutting, chamfering and knurling by adopting the above method is known as lathe.



Turning



View of Lathe

XII BME_English version CHAPTER 01.indd 2 1/8/2020 1:45:51 PM