1.3 Structure of Lathe

The lathe has bed on which head stock is mounted on left end, tailstock at right end and carriage is placed and moved on the bed.

1.4 Main parts of a lathe


Every individual part performs an important task in a lathe. Some important parts of a lathe are listed below.

1. Bed
2. Headstock
3. Spindle
4. Tailstock
5. Carriage
   a. Saddle
   b. Cross – slide
   c. Compound rest
   d. Compound slide
   e. Tool post
   f. Apron
6. Leadscrew
7. Feed rod

LXSIZX

Bed

Bed is mounted on the legs of the lathe which are bolted to the floor. It forms the base of the machine. It is made of cast iron and its top surface is machined accurately and precisely. Headstock of the lathe is located at the extreme left of the bed and the tailstock at the right extreme. Carriage is placed in between the headstock and tailstock moves on the bed guide ways.



Lathe

XII BME_English version CHAPTER 01.indd 3 1/8/2020 1:45:51 PM