12th-Basic Mechanical Engineering-Theory

Model Question Paper

TIME: 2.30 HOURS **MARKS: 90**

PART –A

Choose the correct option **15 x 1 = 15**

1. The inventor of lathe is
   a. Henry maudslay b. Eli whitney
   c. James nasmith d. Michael faraday

2. A part used for taper turning
   a. Cross – slide b. Compound rest c. Saddle d. Apron

3. The lip clearance angle of a drill is
   a. 59^0 b. 118^0 c. 12^0 to 15^0 d. 135^0

4. The groove in the body of the drill is
   a. V-shape groove b. U-shape groove
   c. Flute d. Straight shape groove

5. The operation mainly done in a shaping machine is
   a. Turning b. Drilling
   c. Machining a flat surface d. Thread cutting

6. The part involved in reciprocation by quick return is
   a. Table b. Ram c. Saddle d. Crossrail

7. The heat generated during dry grinding process will be
   a. 20^0 c b. 1000^0 c c. 2000^0 c d. 1200^0 c

8. The hardest natural abrasive is
   a. Sand stone b. Emery c. Diamond d. Corundum

9. In a milling machine, cutters are mounted on
   a. Column b. Spindle c. Overhanging arm d. Arbor

XII BME_English version CHAPTER 10.indd 177 1/8/2020 1:37:58 PM