Basic Mechanical Engineering
Practical


NOTE
All dimensions are given in mm. The diameter of the round rod is given as 20 mm. The design of the exercises may be modified according to the size of the material available.

Points to be considered while working on a lathe
Some important points are to be considered before setting on to work on a lathe. They are

1. The suitable method of holding different types of work according to their shape.
2. Selection of proper cutting speed according to the size, weight, material of the work and the type of the operation.
3. Selection of proper cutting tool.
4. Mounting of the selected tool on the tool post.

The following illustrations are given to provide a good idea of holding a work, cutting speed, types of tools and setting of the tool.

Holding of the work



Holding of the work

XII BME_English version_Practicals.indd 182 1/8/2020 1:50:16 PM