


Gear Box

1. $\frac{A}{D}\times\frac{D}{G}$	2. $\frac{A}{D}\times\frac{E}{H}$	3. $\frac{A}{D}\times\frac{F}{I}$
4. $\frac{B}{E}\times\frac{D}{G}$	5. $\frac{B}{E}\times\frac{E}{H}$	6. $\frac{B}{E}\times\frac{F}{I}$
7. $\frac{C}{F}\times\frac{D}{G}$	8. $\frac{C}{F}\times\frac{E}{H}$	9. $\frac{C}{F}\times\frac{F}{I}$

1.12 Types of lathe

Various designs and constructions of lathe have been developed to suit different machining conditions and usage. The following are the different types of lathe.

1. Speed lathe
   - a. Centering lathe
   - b. Wood working lathe
   - c. Polishing lathe
   - d. Metal spinning lathe
2. Bench lathe
3. Tool room lathe
4. Semi Automatic lathe
   - a. Capstan lathe
   - b. Turret lathe
5. Automatic lathe
6. Special purpose lathe
   - a. Wheel lathe
   - b. Gap bed lathe
   - c. T – lathe
   - d. Duplicating lathe

Speed lathe

Spindle of a speed lathe operates at very high speeds (approximately at a range of 1200 to 3200 rpm) and so it is named so. It consists of a headstock, a tailstock, a bed and toolslide only. Parts like leadscrew, feed rod and apron are not found in this type of lathe.

1. Centering lathes are used drilling centre holes.
2. The wood working lathes are meant for working on wooden planks.

XII BME_English version CHAPTER 01.indd 12 1/8/2020 1:45:53 PM