



3D-Three Jaw self-centering chuck

Three Jaw self-centering chuck



3D-Four Jaw independent chuck

Four Jaw independent chuck

shapes. Concentric circles are inscribed on the face of the chuck to enable quick centering of the workpiece.


Disadvantages

1. It requires more time to set the work aligned with the lathe axis because each jaw is moved independently.
2. Experienced turners can set the work about the axis quickly.

Magnetic chuck

The holding power of this chuck is obtained by the magnetic flux radiating from the electromagnet placed inside the chuck. Magnets are adjusted inside the chuck to hold or release the work. Workpiece made





Magnetic chuck

XII BME_English version CHAPTER 01.indd 17 1/8/2020 1:45:54 PM