
## Chamfering

Chamfering is the operation of beveling the extreme end of the workpiece. The form tool used for taper turning may be used for this purpose. Chamfering is an essential operation after thread cutting so that the nut may pass freely on the threaded workpiece.





Chamfering

## Undercutting

Undercutting is done


1. At the end of a hole
2. Near the shoulder of stepped cylindrical surfaces
3. At the end of the threaded portion in bolts




Under Cutting

It is a process of enlarging the diameter if done internally and reducing the diameter if done externally over a short length. It is useful mainly to make fits perfect. Boring tools and parting tools are used for this operation.

## Knurling






Knuriling



XII BME_English version CHAPTER 01.indd 25 1/8/2020 1:45:57 PM