2.4 Types of drilling machines
2.5 Portable drilling machine
2.6 Sensitive drilling machine
2.7 Up-right drilling machine
2.8 Radial drilling machine and its special features.
2.9 Gang drilling machine
2.10 Multi – spindle drilling machine
2.11 Deep – hole drilling machine
2.12 Size of a drilling machine
2.13 Drill spindle assembly
2.14 Work – holding devices.
2.15 Tools used in a drilling machine
2.16 Twist – drill nomenclature
2.17 Tool – holding devices
2.18 Drilling machine operations
2.19 Cutting speed. Feed and depth of cut
2.20 Safety precautions

Chapter 03 Shaping Machine **57**

3.1 Introduction
3.2 Process of machining
3.3 Main parts of the shaping machine
3.4 Types of shaping machine
3.5 Quick return mechanism
3.6 The size of a shaper
3.7 Adjusting the length of stroke
3.8 Method of table movement
3.9 Pawl and Ratchet mechanism
3.10 Swivel tool head
3.11 Work-Holding devices
3.12 Types of shaper tools
3.13 Setting of shaper table, vice and Tool head
3.14 Types of shaping operations
3.15 Special operations

1_XII BME_English version FM.indd 8 1/7/2020 3:57:20 PM