


T-bolt and clamp

rests on a step of the step block. The different steps of the block are useful in leveling the clamp when holding works of different heights. A nut on the top of the clamp holds the work rigidly. 'T' bolt, clamp & step block.

Angle Plate


Angle plate resembles the English alphabet 'L'. It is accurately machined to have two sides at right angles. Slots are provided on both sides. One of the sides is bolted to the machine table and the workpiece are held on the other side. The use of an angle plate is shown in Figure.

V-block

V-block is a metal block having a 'v' shaped groove on it. It is used for holding cylindrical workpieces. Operations like keyway cutting, slot cutting and machining flat surfaces can be performed on the cylindrical workpieces held on a 'v' block. The use of a 'V' block is illustrated in Figure.

Special fixtures

When internal keyways are to be machined on the holes, the work is held with a special fixture. The fixture has a V-block attached to it and the cylindrical work is mounted on it.



Angle Plate

XII BME_English version CHAPTER 03.indd 68 1/8/2020 1:43:59 PM