ACTIVITIES

1. Visiting the nearby workshop or polytechnic or engineering college for knowing what type of operations done in shaping machine.
2. To make different models shapes of cubic square, cubic rectangle and prism by using wood (or) thermocol sheet.

QUESTIONS

8RV18Q

Part I.

Choose the correct option 1 Mark

1. The shaping machine was designed by
   a. Henry Maudslay
   b. Eli Whitney
   c. Michael Faraday
   d. James Nasmith
2. The operation mainly done on a shaping machine is
   a. Turning
   b. Drilling
   c. Machining a flat surface
   d. Thread cutting
3. The mechanism used to move the shaper table automatically is
   a. Back gear mechanism
   b. Crank & slotted link mechanism
   c. Tumbler gear mechanism
   d. Pawl & Ratchet mechanism
4. The part involved in reciprocation by quick return is
   a. Table
   b. Ram
   c. Column
   d. Crossrail
5. The ratio of forward stroke time to return stroke time is
   a. 3:2 b. 5:3 c. 1:3 d. 1:2
6. The part used to lift the tool while the ram moves the returning stroke
   a. Tool-head
   b. Work-table
   c. Clapper-block
   d. Cross-slide

Part II.

Answer the following questions in one or two sentences 3 Marks

7. Define “Shaping”.
8. List any four parts of shaper.
9. What is the use of crank & slotted link mechanism?
10. Define “cutting speed” of shaping machine.
11. Define “feed” of a shaping machine.
12. Mention the “depth of cut” of shaping machine.
13. What is the use of a clapper box?
14. What is the use of swivel tool head of a shaping machine?

XII BME_English version CHAPTER 03.indd 75 1/8/2020 1:44:01 PM