8.13.4 Vehicle Pulling on one side

Sl. No.	Possible cause	Remedy
1	Uneven tyre wear	Tyre rotation
2	Improper brake adjustment	Check and adjust the brakes
3	Failure of damper / spring in one side	Replace the damper / spring

Student Activity

1. Students are advised to submit a report based on the visit to the nearest automotive workshop to study about various parts in steering system and its assembly procedure in vehicle.
2. Students are advised to submit a report on construction and working principle of steering system used in Modern cars with sketches based on the visit to the nearest Automotive workshop.

Glossary

1.	Alignment	–	ஒழுங்கமை
2.	Axle	–	அச்சு
3.	Kingpin	–	பிரதானபின் [சுழல் மூட்டுக்கம்பி]
4.	Camber angle	–	மேல் சாய்வு கோணம்
5.	Ball joint	–	பந்து கிண்ண இணைப்பு
6.	Steering	–	திசை திருப்பி
7.	Worm	–	திருகுருவப் பொருள்
8.	Power steering	–	விசைத் திருப்பி
9.	Irreversibility	–	மீளாத்தன்மை
10.	Stub axle	–	துணை அச்சு

References

1. S.K. Gupta, A Text Book of Automobile Engineering, S. Chand and Company, New Delhi, ISBN 978-93-837-4691-0, First Edition 2014, Reprint 2016.
2. Automobile Engineering, 2nd Edition, Sci Tech Publications (India) Pvt Ltd, 2011. Ramalingam. K.K.
3. Kirpal Singh, Automobile Engineering, Vol 1, Standard Publisher and distributor, ISBN – 13 – 978-8180141966

BAE_ENG_Chapter_08.indd 163 12/10/2019 12:11:21 PM