


Practical – 9
DYNAMO

Aim
Dismantling, inspecting and assembling the & given dynamo.

Equipments required
Given Dynamo

Tools required
1. Ring spanner
2. Double end spanner
3. Screw driver
4. Drift punch
5. Wooden hammer
6. Armature growler
7. Insulation tester
8. Puller
9. Copper hammer

Material required
1. Cotton waste
2. Kerosene

Reasoning for dismantling
- No current supply through terminals
- More noise when the generator is running
- Low output current in dynamo
- Damage armature bearing
- Manufacture of POI is over

BAE_Practical.indd 254 12/20/2019 2:35:37 PM