perpendicular to each other. The gear which looks like a spur gear is called as the worm. The small shaft with the single start thread or multi start thread cut made on it is called the worm shaft. This type of gear is used in places where high speed reduction and high power transmission are obtained. It is used in steering gear box in automobiles.




Figure 3.2.1.5 Worm and worm gear

3.2.1.6 Double helical gear or herringbone gear

On the circular periphery of the cylindrical metal teeth are cut in the shape of the English letter "V". This gear is called as double helical gear or herringbone gear. This type of gear is used where more rotational power (torques) is transmitted.




Figure 3.2.1.6 Double helical gear of herringbone gear

3.2.1.7 Internal gear

The internal gear is the one in which the teeth are cut internally on the inner circular metal pipe. This is called as the internal gear. This gear could transmit more power in short places. They are strong in structure. They are used in a small mechanisms and tractor mechanism.




Figure 3.2.1.7 Internal gear

3.2.1.8 Sprocket wheel

On a rounded metal wheel plate teeth are cut outside. This wheel is not in direct contact with the other wheel. In between the two wheels a chain is placed and the rotational power is transmitted through the chain. It is used in timing gears. Moreover it is also used in motor cycles.



Figure 3.2.1.8 Sprocket wheel

BAE_ENG_Chapter_03.indd 33 12/10/2019 11:28:11 AM