


₹1 CROORE
Cost of repairs in 2007

₹2 CROORE
Cost of repairs and renovation this year





60 FEET
Height*

765 FEET
Length

4.5 FEET
Width

*from the ground at the time of construction

MAINTENANCE AND REPAIR

- Shut down for maintenance work at least a dozen times
- After the 2001 earthquake, which caused serious damage to the bridge, it was shut for two years for repairs
- The Oreva Group, makers of Ajanta clocks and e-bikes, was given charge of the bridge's maintenance in 2007
- On March 7, 2022, the Oreva Group signed a 15-year contract to maintain and operate the bridge
- Shut down in March 2022 for repairs and renovation
- Reopened on October 26, though the contract specified that it had to be kept shut for 8-12 months during repair work

HOW THE BRIDGE COLLAPSED

- Based on the available visuals and eyewitness accounts, one of the two suspension cables seems to have snapped, triggering a cascading effect that led to the breaking of the deck
- Another possibility is that the connections securing the vertical cables with the deck broke, especially at one end of the bridge, letting the unsuspended section with the people on it fall into the river
- The bridge was overcrowded
- Excessive swaying of the bridge has been suggested as another possible factor that needs to be probed
- The original wooden deck was replaced with a heavier aluminium one during recent repairs, but the cables were not strengthened. This caused greater strain on the connecting mechanism