

AMD High-end Graphics Motherboards							
Brand	ASUS	Biostar	ECS	Gigabyte	Gigabyte	Jetway	MSI
Model No.	M4A79T Deluxe	TA790GX A3+	A790GXM-A	MA790FXT-UD5P	MA790GP-UD4H	HA07 Ultra	790GX-G65
Price (Rupees)	Rs. 14,850	Rs. 6,395	Rs. 6,390	Rs. 14,990	Rs. 9,900	Rs. 5,500	Rs. 9,000
Overall (Out of 100)	66.27	60.73	56.61	65.48	61.73	62.00	65.84
Features (Out of 70)	40.91	35.52	31.43	40.47	36.06	36.37	40.65
Performance (Out of 30)	25.36	25.21	25.18	25.01	25.67	25.63	25.19
Features							
Chipset	AMD 790FX	AMD 790GX	AMD 790GX	AMD 790FX	AMD 790GX	AMD 790GX	AMD 790GX
Socket	AM3	AM3	AM2+	AM3	AM3	AM2+	AM3
Northbridge / Southbridge	790FX / SB750	790GX / SB750	790GX / SB750	790FX / SB750	790GX / SB750	790GX / SB750	790GX / SB750
Memory Type	DDR3	DDR3	DDR2	DDR3	DDR2	DDR2	DDR3
Max Memory Supported (GB) / No of DIMMs	16 GB / 4	16 GB / 4	32 GB / 4	16 GB / 4	16 GB / 4	8 GB / 4	16 GB / 4
No. of SATA / IDE Ports	5 / 1	6 / 1	6 / 2	6 / 1	6 / 1	4 / 1	5 / 1
E-SATA Support / No of E-SATA Ports	Y / 1	N / 0	N / 0	N / 0	N / 0	Y / 1	Y / 1
No of PCI Express x16 graphics slots	4	2	2	2	2	2	2
No. of PCI / PCI x1 / PCI x4 Slots	1 / 0 / 0	2 / 2 / 0	2 / 2 / 0	2 / 3 / 0	2 / 3 / 0	2 / 2 / 0	2 / 2 / 0
Multi GPU Support (SLI/CrossFire/N) / No of PCIe Lanes	Y / 4	Y / 2	Y / 2	Y / 2	Y / 2	Y / 2	Y / 2
Integrated Audio Controller	Realtek 1200	Realtek ALC888	Realtek ALC888S	Realtek ALC889A	Realtek ALC889A	Realtek ALC888	Realtek ALC889
Number of Sound channels	8	8	8	8	8	8	8
SPDIF / Optical Port	Y / Y	0 / 0	N / Y	Y / Y	N / Y	Y / N	N / Y
No of LAN Ports / 10/100 / Gigabit	1 / Gigabit	1 / Gigabit	1 / Gigabit	2 / Gigabit	1 / Gigabit	1 / Gigabit	1 / Gigabit
Integrated Wi-Fi (Y/N)	N	N	N	N	N	N	
No. of rear USB / FireWire Ports	6 / 1	4 / 1	6 / 0	8 / 2	4 / 1	4 / 0	6 / 1
All Solid State Caps (Y/N)	Y	Y	N	Y	Y	Y	Y
BIOS options							
CPU voltage range (volts)	0.8 ~ 1.7	0.02 ~ 1.26	NA	0.825 ~ 2.025	0.825 ~ 2.025	0.8 ~ 1.55	1.1 ~ 1.55
CPU Voltage increments	0.0125	0.02	0.02	0.025	0.025	0.025	0.0125
Memory voltage range (volts)	1.5 ~ 2.5	1.66 ~ 2.84	NA	Default + 0.75	Default + 0.75	1.7 ~ 2.85	1.5 ~ 2.42
Memory Voltage increments	0.02	0.02	0.01	0.05	0.05	0.05	0.05
Board Layout (So 10)							
Region around the CPU	8	8	8	7	7	7	8
Location of SATA ports	7	7	6.5	8	8	7	8
Placement of Memory modules	7.5	8	8	7	8	8	8
Graphics card slot and PCI slots	7	8	8	8	8	8	8
Package Bundle							
No of SATA / PATA Cables Provided	3 / 0	4 / 1	2 / 1	4 / 2	4 / 1	2 / 1	4 / 1
Accessories	-	-	-	-	-	Switch Card	Molex to SATA power x2
Performance							
PC Mark 05							
CPU	10282	10271	10266	10291	10366	10277	10262
Memory	6210	6288	6152	6481	6795	6797	6136
Graphics	23353	13500	14695	14929	15201	14573	14832
HDD	8803	8760	8806	8745	8835	8771	8717
Overall	10097	9917	10109	10367	10275	10376	10145
ScienceMark (Memory Bandwidth)	9064	9616	8358	6905	9779	9493	8788
3D Mark Vantage							
CPU	37184	35584	35927	36578	36778	35952	36780
GPU	6959	6756	6958	6956	6990	6917	6952
Overall	8734	8471	8715	8722	8764	8667	8720
Cinebench R10	11134	11094	11056	11150	11162	11074	11104
WinRAR 3.8	2363	2371	2210	2293	2388	2352	2248
DivX Video Encoding (100 MB VOB) (sec)	31	30	30	32	30	30	31
Sequential File Transfer (8 GB File) (sec)	163	166	161	165	170	161	165
Random File Transfer (8 GB File) (sec)	193	186	188	190	192	189	189
STALKER Clear Sky (1280 x 1024, low)	79	76.1	78.2	80.1	79.9	79	78.5
Crysis (CPU - 1024 x 768, low)	68	61	64	68	67	64	67
Crysis (Graphics - 1280 x 1024, high)	45	42	44	44	44	44	45

would be a great HTPC board but it comes with no HDMI port. The only PCIe x1 slot would be useless because of the first PCIe x16 slot.

This entry-level Jetway

PN78VM2-LF runs on the GeForce 8100 chipset yet packs a punch for its low price. Even though it's a basic board, a big metal plate at the back ensures the board doesn't flex. There

are the solid-state capacitors in the important regions of the board. The heat sink is made of thin gauge aluminium but it works rather well for this chip. There's also a HDMI port built

into it which makes this board ideal as a base to build a HTPC on. The only PCIe slot is above the primary x16 slot. The high heat sink completely comes in the way of the slot.