

Hacking consoles

Hacker claims to have finally cracked the PlayStation 3

Nexus gets multi-touch

Google releases firmware to enable multi-touch functionality to the Nexus

vide me the link to your page where I can find the BIOS files to download. I also want to over-clock my graphic card. For the time being, I've set the values of core, memory and shader to its default values - 575, 400 and 1375 MHz, respectively. I want to know what values I should use to overclock my GPU without harming it. My PC configuration is as follows: Intel P4 3.06 HT, 1.5 GB DDR1 RAM and 250 GB HDD.

Abhishek Rathor

The graphic card brand you might be referring to is WinFast from Leadtek. Updating the BIOS of a product is unnecessary unless there are some major issues. A wrong BIOS update or a problem during flashing could make the card unusable. The limits to which any component can be overclocked isn't set. It's something that has to be done little by little till you reach a point where there is both a performance boost and also stability. A poor cooling solution will also limit you. Keep checking the temperature of the card every time you make an incremental over-clock. The 9400GT isn't a very powerful card and overclocking it won't give you a big boost in performance. Do it at your own risk.


Norton won't go

My PC configuration is Processor - Intel Pentium 4 2.93 GHz RAM - 256 MB DDR

I have installed Norton Internet Security and now I want to remove it. But when I uninstall it, I'm not able to access the Internet. When I install again, the connection works fine. Please help me uninstall it.

Shubham Kesarwani

The problem might be due to some permission set by Norton Internet Security. Make



Ensuring Windows Firewall is working once a security suite is uninstalled

sure NIS isn't running when you uninstall the program. Once uninstalled, check the Windows Firewall to make sure it is enabled but more importantly to check if connections are being allowed.

Tri-core performance

I'm a post graduate student in VLSI Design. I'm facing problems with my PC, which has the following configuration:

- AMD Phenom x3 8650 2.3 GHz processor
- ASUS M3N78-EM motherboard
- 2 GB DDR2 ZION RAM
- 160 GB Seagate HDD
- BSNL broadband connection
- ASUS VH192 19-inch monitor

I use Windows XP SP2. The system boots slowly and after booting, it takes time to connect online and also it requires more time for opening any application such as Media Player and Nero. In fact, it takes

some time to settle, only then can any application be run without freezing the system. As the processor has three cores, I expect the system to run faster than my earlier dual core processor which is not happening. I heard that the triple core processor from AMD isn't very great. I am playing Max Payne 2 on the system, but it runs very slowly while it works

pretty well on an Acer laptop which has an Intel Core 2 Duo processor. Please help in sorting out the issue.

Will a transition to the following configuration makes

my system better? AMD Athlon II X2 245 with an ASUS or Giga-byte suitable motherboard.

I'm having a problem with my monitor also. A weird shade runs from the bottom to top continuously. I use iBall speakers. Are these speakers affecting the monitor? I switched off the speakers

and checked but the problem remains. I took the monitor to the service centre and it was working fine there. I do not know what to do.

Madhu

The slowdown could be due to a number of reasons. If you haven't installed any drivers for the motherboard. It can, in some cases, severely affect performance. Download and install the latest drivers for the board from the manufacturer's site. If you're using an old PATA hard drive, that too can slow down the PC. Run virus scans to be sure that there are no viruses on the system.

The Athlon X2 245 is a faster processor for single threaded applications, but the Phenom x3 8650 isn't very slow either like you mentioned. A tri-core doesn't automatically mean a faster user performance. Not all applications can use multiple cores efficiently, so in applications where a single core is used, clock speed of the processor determines the performance. A dual running at 3 GHz will then definitely be faster than a 2.4-GHz tri-core. The laptop you have might have a better graphics solution than the onboard graphics of the AMD 780G chipset, which is why you see a stark difference. First, rectify the bootup and slow application loading issues and then invest in a decent graphics card for gaming.

LCD monitors shouldn't be affected by magnetic fields from speakers like with CRTs. It could be some problem with the panel itself. Also, check the cable for damage and if possible, test the monitor on a different PC or using a D-sub instead of DVIs.

