




There really is no comparison between the Pi and its contemporaries. (<http://dgit.in/PiVsAll>)

replaces the former Broadcom 2835 SoC (System on a Chip) foundation. In addition to which the former single core 700 MHz ARMv6 processor is replaced with the new quad-core 900 MHz ARMv7 Cortex-A7 processor. While this doesn't radically alter the physical design of the chip there is a minor power consumption uptake and subsequent heating issue if the chip is overclocked.

Despite the changes that come with a new board, such as ARMv7 modules and kernel, it will not obstruct compatibility with ARMv6 user space binaries and will run existing Linux distributions for the original Raspberry Pi. The only flaw of note is an amusing one - the Raspberry Pi 2 is "camera shy". This fault was discovered when the microcomputer was being photographed with a Xenon flash. In certain specific cases, the high intensity of the flash can cause a hiccup in the voltage flow causing it to reboot. This problem is due to a photoelectric effect, which is when metals give off electrons when hit by light. This problem is easily fixed by putting a tiny opaque cover on the U16 chip between the power supply USB and the HDMI port. Clearly this flaw hasn't lessened the excitement of Raspberry Pi's core and dedicated following since the initial stock of the Pi 2, which was of 150,000 units was sold out in no time. And the company continues to manufacture 20,000 computers per day to meet the increasing demand.

The Cost of Keeping Costs Low

There are two broad criticisms of the Raspberry Pi - they're not that cheap