



WHAT IS THE DEAL WITH HIGH REFRESH RATE DISPLAYS?

High refresh rate was supposed to be the panacea for modern flat screen panels, which were marred by slow response times that caused blurring in scenes with a lot of motion. That problem has largely been addressed, but the blurring issue still exists because the human brain has a hard time processing motion with flat panel TVs. That's why LCD TV manufacturers add either switch off the backlight between frames, add blank frames, or otherwise emulate the electron scanning beam of CRT TVs by turning off individual rows of backlights. This bumps up the default refresh rate of 60 Hz to 120 Hz. This is further increased to 240 Hz and beyond by employing image processing to interpolate intermediate frames. In effect, high refresh rate TVs are essentially bump up the regular refresh rate of 60 Hz using backlight scanning and frame interpolation.

lot on calibration tools and software, there's a free alternative that still gives pretty stunning results provided you know what you're doing.

In all probability you probably don't know how to go about calibrating your display without any hardware or fancy software calibrators, but don't fret because we have got that covered. Like most free stuff, this free calibration tool too comes from the generous land of Europe. Netherlands to be precise, where a university has released some handy and reliable suite of display calibration test images on its website. Here's what you need to know about using these free test images to calibrate your display using only your eyes.

Calibrating the Display With Your Eyes

Before we begin to tweak any settings, it's important to tone down the horrendous default

settings and image "optimisations" the manufacturer has dialled up to vie for your attention in the showroom. First off dial down the brightness levels down to anywhere between 35 to 40 percent, depending upon which level gets you the deepest blacks. Don't fret about getting things perfect at this juncture, we shall be doing that later with the help of calibration images. The contrast setting should be kept at anywhere between 70 to 80 percent prior to final calibration.

This will sound counterproductive, but go ahead and switch off absolutely all picture enhancement gimmicks without any exception. This