



USS Vincennes

A well design and thoughtful UI would have easily solved this issue. In fact one report says that one of the engineers in the Aegis software system even suggested a few UI changes but was dismissed by the logic that they would only deliver on what the Navy required and nothing more.

A clear and concise UI is an implicit requirement of design and need not be explicitly mentioned to be implemented.

Case 4: Scud missile hits american barracks

In another mishap that resulted in the loss of human life, a scud missile hit the American barracks without being challenged at all by the ultra-modern Patriot defense system put in place. The root of this was a time delay error that was caused due to a combination of exception situations. The running time was exceeded and there was also a floating



Yes, that's a SCUD missile