



Anti-kink coils will prevent kinking at sharp bends on soft tubing

in soft tubing that hinders with the flow of the fluid and sometimes might even stop the flow. Avoid them using anti-kink coils. They are usually installed near the fittings where the radius is tight on the tubes. Ultimately, they also improve the flexibility of the tube. Another way to avoid kinking is to use thicker soft tubing.

Cables, adapter and splitters come in handy if your current hardware is limited. It's always best to buy the latest hardware and check for compatibility with the rest of your components. You

will mostly face issues with cable connectors and sometimes the length. Fret not, because you can buy cable extensions for almost every component. If you fall short of connectors, you can go for splitters.

Coming to the tools, some of them are essential while the rest are optional. You will obviously need screwdrivers to disassemble your components, attach the water blocks and install the other parts inside your chassis. You might also need an Allen key or hex key to tighten the fittings. Since you're dealing with fluids that can damage your components, you will need lots of paper towels. A measuring cup will be essential when you're pouring the fluid into the reservoir and loop. It's best to go for a filling bottle that has a pipe and measurements marked on it so that you can have best of both worlds in the same bottle. It makes the process of filling and draining the liquid cooling loop way easier.



Splitters are useful when you fall short of fan headers on your motherboard

To know how much tubing you need, you will require measuring scales. Your tools will also be dependent on the type of tubing you're going to use. If you're dealing with soft tubing, then you can do fine with a normal blade or you can go for expensive cutters dedicated to cut soft tubes uniformly. When you're dealing with hard tubing, you will need way more