




# Cooling your PC

Heat is practically the arch-enemy of electrical components aside from water. Here's why it's bad for your PC.

**H**eat is an unavoidable outcome of anything powered by electric current. The friction caused by electrons bumping into atoms results in some decent heat generation and when you have a lot of electrical components within a very small space, things heat up pretty quick. Needless to say, heat and electronic components don't gel with each other. You've obviously seen the outcome of excess heat in the form of gadgets that have gone up in smoke. Remember that old cloth iron that let out a couple of buzzing sounds before ending up dead? That probably happened when the rubber sheath melted off and led to a short circuit. Or perhaps that overloaded power brick which had way too many high-draw devices connected to it that tripped the circuit breakers in your home.