

Step 7: Connecting USB risers

The graphics cards should be securely mounted to the frame using the USB riser. Connect your GPU's PCI-e 6+2 power connections. All of these connections must be connected to the remaining 5 GPUs afterwards.

Step 8: Finishing Touches

Finally, double-check that the cords are properly connected. The graphics card, which is attached to the primary PCI-E slot should be connected to your display.

After connecting the mouse and keyboard, continue to turn your rig on. Connect the power switch to the motherboard's power pins to do this. If you're not sure where to look, see the motherboard handbook.

If it boots, it's an indication that the rig is operating well. When everything is successfully installed, you will see the BIOS message come up on your screen.

Conclusion

Anyone, regardless of technical aptitude, can construct a crypto mining setup with a decent tutorial. Even with no technical skills, you can create your own cryptocurrency miner. If you want to build your own cryptocurrency miner for passive income, it is advised that you create a budget for components and estimate the monthly return. This will offer you a break-even point, where if you sell your earnings on a regular basis, and break-even after a specific length of time. Selling your mined cryptocurrency on a regular basis allows you to dollar cost average your investment, making it considerably safer in the long run. 