

## Risers

Risers are responsible for most of the problems with GPUs. So, for example, if you have a problem with one of your GPUs and it doesn't show up or you can't flash the BIOS, try replacing the riser. The company is trying to get a high-quality riser (VOO9S). These are very important parts of the mining rig and should not be a problem. 444-460cm cable length is fine.

## Disk

- For 6 GPU mining rigs get 64GB SSD
- For 12 GPU mining rigs get 128GB SSD

## Which GPU do you want to buy?

- Check the profitability of the GPU and the time it takes to recover your investment.
- You can get Windows 10 Pro for free from the official website.
- Download Windows Tools to create a bootable USB stick (if you do this on a PC that already has genuine Windows installed) or download the Windows 10 ISO from the website to create a bootable USB stick and install Windows.
- With SSDs, you don't have to pay for a license if you don't need it. The GPU is not connected to the mining rig!
- The first thing is to optimise Windows mining purposes. This is the most important part of what people are doing wrong! If you need the original Windows 10, buy it from Kinguin.
- The only difference from the OEM version, not the retail version, is that you can only activate Windows on one PC (you cannot reactivate the key on another PC).
- This version is the most loved one by the miners

## Why Windows instead of Linux?

- Most people think Linux is a more stable operating system. It is also often believed that Linux is so lightweight and well-behaved that you can increase GPU support (Windows 10 now supports 12 GPUs) and you need the right option for 24/7 mining.
- Looks logical, but it's not. Linux has a variety of issues, including GPU drivers on Linux are old and poorly supported and the fact that even though overclocking tools for Linux are available but they are