

cisely as shown. Otherwise, the profile settings will not be applied properly until you apply the settings first and then click the “Save” button beside the profile. You’ve finished setting up your first GPU and are ready to go on to the FINAL STEP.

Remember to Overclock Properly

Overclock and undervolt both don’t have the same value. There are no ideal or universal values as the same Overclock/Undervolt settings do not function the same way on identical GPUs. Each GPU is unique, and optimising it effectively requires specific testing.

In order to get the right optimisation, you can download the tool HWiNFO64.

Install and run it. Remember to run it in Sensors-only mode.

Then scroll all the way down until you see your GPUs at the bottom. Select all sensors except “Memory Errors” and HIDE them when you’ve discovered the GPUs.

- Begin mining with the existing basic parameters, just like we did with the first GPU on the Memory, with a goal temperature of 60.
- If no memory problems appear, the present setting is correct; however, it will take around 2 minutes to check if any appear.
- Now set the RAM to 1850 MHz, hit apply, and finally save the profile.
- Now run the “overclock.bat” script to restore the GPU’s normal settings, after which you’ll need to apply the new 1850 MHz memory settings.
- Start mining and check if you receive any memory issues.

