



Bernie under the FBI scanners

Senator Sanders and his wife are under the FBI's radars regarding an earlier loan borrowed by Mrs. Sanders. <http://digit.in/BernieFBI>



Huge ice shelf reaching its end

Antartica's Larsen C, one of the largest ice shelves ever has developed a crack that is just 13km off the edge. <http://digit.in/Antshelf>

Teardown: Surface Laptop

Microsoft's latest addition to the Surface family of devices has received a lot of flak for being too generous with glue making it not at all repairable. Here's how Microsoft could have done better.

Mithun Mohandas | mithun@digit.in

That's a Big battery!

These new ultra-thin laptops have made it really painful to get to. The Surface Laptop's battery, while large in capacity, is the last thing you can remove during disassembly. A hatch on the bottom could have easily changed that for the better.

Mainboard

Putting the mainboard near the screen and the battery near the user is a smart move since it results in reduced touch temperature under heavy load conditions.



Weld me not

The metal shield underneath the Alcantara layer could have easily been a slide-in on three sides with a screw on the remaining side.



Port ahoy!

While the 3.5mm jack is modular, the USB ports aren't. This could have easily been a daughterboard.