

World's fastest A4 desktop printer

The Machjet LPP1060N is twice as fast as a regular printer, capable of outputting a 1600x800 print at 60 pages per minute - without burning the page!

Massive BitCoin selloff

The first completely digital currency suffered a massive selloff due to a compromised account with rates going from 17 dollars to a cent!

The print quality, of photos printed on the K109a, was largely good, with prints churned out pretty quickly. All through the three test images - Photo 1, 2, 3 - we felt the K109a played second fiddle to the OfficeJet 6000 or the Canon Pixma iP4870, whether it was the quality of printed photos or the time taken to print them. Even for mixed document printing, the printer took the longest time to print the document with the third best print quality - that isn't exactly stellar performance. However, this is the cheapest, most portable printer in the comparison - without any frills.

HP OfficeJet 6000 - e609a

The OfficeJet 6000 e609a series printer is a touch larger than the K109a. With intended usage beyond just home users, the OfficeJet comes with extra features - like a LAN port, for sharing the printer in an office environment and duplex printing support. It also has CMYK cartridge slot, with slim cartridges (C,M,Y,K) that are installed by popping the hood of the printer - cartridge installation, much like the K109a, is easy peasy.

Driver installer is heavy from the web - over 200MB - and it's good that HP has included a detailed manual and driver CD. It also has proprietary HP software which lets you monitor the cartridge's ink levels, update drivers, etc, right

from your computer. The printer is easy to setup and get started with. It's a dreary mass of black with nice, prominent buttons that are good to click on. The printer also has additional features such as Wi-Fi and Ethernet printing support, which gives it extra points in our comparison table.

The OfficeJet 6000 e609a is physically larger than the K109a, and takes up larger desk area. Its tray is similar to the K109a, but thankfully it's a touch longer. Output prints barely fit into the tray's area, although paper doesn't really spill over - the OfficeJet 6000, unlike the K109a, doesn't spit out the prints either, which helps keep the paper in the tray.

In terms of performance, the HP OfficeJet 6000 e609a was one of the star attractions. Not only did it rake in one of the highest points in terms of pure performance (time taken and quality of prints), it's also one of the most feature-rich printers in this comparison test - remember, photo-only printers are severely curtailed, stripped down boxes in



Epson L100
Price ₹9,999

the features department compared to their MFD brethren. Colour, detail, and black levels were much better in our test photo prints on the OfficeJet 6000 e609a compared to the HP K109a. However, mixed document printing isn't great at fast document mode, and the printer falls short of expectations. Overall, this is a great buy if you need a feature-rich, quality photo printer at an attractive price.

Epson L100

The Epson L100 comes with a tall claim of being the world's first original ink tank system printer. It has a tiny 14MB driver installer that is very convenient to download and setup off Epson's web site.



HP OfficeJet 6000 - e609a
Price ₹4,999

The L100 is a glossy black monolith mass with a back-loading paper tray and a front output tray. The output tray is detachable and flimsy in build quality. Overall, the Epson L100's build quality isn't as great as the two

HP printers. Its cartridge compartment sits exposed to the left of the printer (C,M,Y,K) - these are vertical columns, compartmentalized sections, made of white plastic. One can easily see ink levels from the side, no need for a software to see it on your desktop screen - which we feel is a rather a convenient addition.

Epson also provides refill ink bottles for all four colors with the printer. But we witnessed they weren't packaged well, as a couple of ink bottles were squished and one had leaked ink - the problem we found was its packaging, it wasn't in styrofoam (like the two HP printers) but only hard cardboard paper, and as such not sufficiently reinforced to absorb shocks and jolts during transportation.

After wasting a lot of time figuring out why the ink bottles weren't firing away to print copies of images, we noticed that merely installing the driver from the website is insufficient to get this printer working. You have to enter the serial number of the ink bottles during setup (through CD) to start using the printer... and wait for 20 mins (according to the manual) to heat up the inks enough. Although we under-