



SATA Raid drivers installation screens

py that contains the RAID driver, and the drivers will be automatically installed.

4. After this you will get a blue screen providing you with options to a) install Windows XP, b) go to the Recovery Console, or c) quit the installation. Press Enter to continue with Windows XP setup.

Windows XP setup options screen

