

coloured dots till the cartridge locks into position. If the problem persists, the most likely cause is a mechanical fault due to fluctuating voltages, and you might have to get the printer serviced.



Inkjet Printer Cartridge

► **Problem:** On a peer-to-peer network connection, you are able to connect all the systems, but are unable to share the print

er amongst all the systems. For example, you might be able to connect the printer only with the first, fifth and sixth system.

Cause: The File and Printer Sharing service is improperly installed.

Solution: Right-click the Network Neighbourhood icon, select Properties, and make sure you have “File and Printer Sharing for Microsoft Networks” installed on the machine to which your printer is connected. Also make sure you enable “Print Sharing” in the “File and Printer Sharing” settings. Then, check that your client PCs have “Client for Microsoft Networks” installed, and are mapping their printer driver to the network port instead of a local port. Also, ensure that you set up the protocols for all the machines properly.

► **Problem:** Windows 98 SE hangs whenever you try to take a printout. The printer LPT port properties shows basic configuration 0000 with input/output range 0378 - 037F, 0778 - 077B, interrupt request 07 and Direct Memory Access 03, with no conflicts.

Cause: This could be due to Improper configuration of the parallel port in the BIOS and/or an IRQ conflict.

Solution: Go to your BIOS settings and check whether your parallel port is configured as ECP mode + EPP mode. Next, check whether your printer is assigned IRQ 7, and whether any other hardware is utilising the same IRQ.

If your printer is not assigned IRQ 7, make sure you assign this