

Code 15

Code Meaning: (Not applicable to Windows XP) The device is causing a resource conflict.

Recommended Resolution: Run `msinfo32.exe` to get more information on the conflict. Check the Resources tab to get details of the conflict. Refer to the hardware documentation and/or the manufacturer's Web site for instructions on the correct values that need to be set manually. Clear the "Automatic Settings" checkbox, click the "Change Settings" button, and input the values.

Code 16

Code Meaning: The device is only partially configured and Windows could not find all the resources required by this device.

Recommended Resolution: Run `msinfo32.exe` to get more information on the conflict. Check the Resources tab to get details of the conflict. Refer to the hardware documentation and/or the manufacturer's Web site for instructions on the correct values that need to be set manually. Clear the "Automatic Settings" checkbox, click the "Change Settings" button, and input the values.

Code 17

Code Meaning: (Not applicable to Windows XP) The hardware is a multi-function device whose driver file is reporting invalid information on how to split the resources.

Recommended Resolution: Remove the device from Device Manager and reinstall it using the Add Hardware Wizard. Use an updated device driver if required.

Code 18

Code Meaning: The drivers for this device should be reinstalled.

Recommended Resolution: Select the driver tab and click the "Update Driver" button. Use an updated device driver if required.

Code 19

Code Meaning: A problem with the Windows Registry entry for this device was detected.

Recommended Resolution: In Windows 9x/ME/2000, run the