

this will tell the buffer to retry any writes to the bus. Disable it if you face performance issues and your PCI bus has high-bandwidth devices. Many retries will jam the bus.

PCI Delay Transaction/PCI 2.1 Compatible/PCI 2.1 Compliance

Options: Enabled, Disabled

Recommended Setting: Enabled

Explanation: A buffer between the faster PCI and the slower ISA. If enabled, may cause problems with some sounds cards. Look for driver updates for the cards.

PCI Dynamic Bursting

Options: Enabled, Disabled

Recommended Setting: Enabled

Explanation: PCI devices write to this burst buffer, and the buffer writes to the PCI bus when it is free or the buffer is full.

PCI Latency

Options: 16 to 255

Recommended Setting: It varies. It's usually set to 32 or 64.

Explanation: This controls the time a PCI device is allowed to use the bus.

PCI Master 0 WS Write

Options: Enabled, Disabled

Recommended Setting: Enabled

Explanation: Disabling puts a 30ns write delay for PCI busmasters. Disable this if you are facing issues with SCSI or a NIC.

PCI Master Read Caching

Options: Enabled, Disabled

Recommended Setting: Disabled

Explanation: Caches PCI Master reads to the CPU's L2 cache. Will cause a performance hit on the CPU if enabled.

PCI Master Pipeline Req/PCI Pipelining

Options: Enabled, Disabled