

has been designed as a distributed program (that is, it spreads the work among large numbers of computers to find the prime numbers). For stress-testing the system, the user needs to click on the “Just Stress Testing” button when running the program for the first time.

To test the computer, run Prime95 and click the Options menu and then select “Torture Test”. Then select a test and click OK. Run the test for a few hours.


If you want to be thorough, then let it run for 24 hours. To stop the test, click the Test menu and then click Stop.

Prime95 checks its calculations against known results, so if something goes wrong it will stop automatically. It’s also been known on certain occasions to crash unstable machines. If it crashes or finishes with an error, then there is a problem with your hardware.


5.2.3 SystemTap GUI (<http://sourceware.org/systemtap>)

SystemTap simplifies the gathering of information about the running Linux kernel, and therefore, assists in the diagnosis of performance or functional problems. It eliminates the otherwise tedious and detailed sequence of work to collect data.

SystemTap comes with a simple command line interface and scripting language. SystemTap in its current state of development



It’s even called the Torture Test!



Who’s the biggest prime of all?