

provided by the PCIe bus, so there are additional power sockets on the card. Power supplies with the 6-pin connector are labelled SLI / CrossFire Ready.

○ **SATA power connector**

SATA drives require a different 15-pin power connector. Most motherboards bundle a 4-pin Molex-to 15-pin SATA converter.

3.1.12 SMPS Fan

The fan is used to cool the components in the SMPS. Since it sucks air out of the cabinet, it also helps reduce the temperature of the system.

3.1.13 Y-Splitter

This is used to increase the number of free power connectors. The Y-splitter consists of two pins on one end and a socket on the other. The socket is used to connect to any Molex converter. This is usually seen associated with additional cabinet fans.



A 4 pin floppy drive connector



A 6 pin PCI-E power connector



A SATA power connector



A Y-splitter to power more devices