

I2C I/O	I2C_ISR_STATE()	I2C_SlaveAddr()	I2C_WRITE()	
	I2C_POLL()	I2C_START()		
	I2C_READ()	I2C_STOP()		
PROCESSOR CONTROLS	CLEAR_INTERRUPT()	GOTO_ADDRESS()	RESET_CPU()	
	DISABLE_INTERRUPTS()	INTERRUPT_ACTIVE()	RESTART_CAUSE()	
	ENABLE_INTERRUPTS()	JUMP_TO_ISR	SETUP_OSCILLATOR()	
	EXT_INT_EDGE()	LABEL_ADDRESS()	SLEEP()	
	GETENV()	READ_BANK()	WRITE_BANK()	
BIT/BYTE MANIPULATION	BIT_CLEAR()	MAKE8()	_MUL()	SHIFT_LEFT()
	BIT_SET()	MAKE16()	ROTATE_LEFT()	SHIFT_RIGHT()
	BIT_TEST()	MAKE32()	ROTATE_RIGHT()	SWAP()
STANDARD C MATH	ABS()	COSH()	LABS()	SIN()
	ACOS()	DIV()	LDEXP()	SINH()
	ASIN()	EXP()	LDIV()	SQRT()
	ATAN()	FABS()	LOG()	TAN()
	ATAN2()	FLOOR()	LOG10()	TANH()
	CEIL()	FMOD()	MODF()	
	COS()	FREXP()	POW()	
VOLTAGE REF	SETUP_LOW_VOLT_DETECT()	SETUP_VREF()		